






[Attachment] Plan Overview



- Major issues with current station building**
- (1) Too many pillars, obstructed vision
 - (2) Relative height differs from West Entrance; divided into parts
 - (3) Seismic reinforcement needed



Station raised to 3rd floor



- Features of planned building**
- (1) A bright, open concourse
 - (2) West Entrance directly connected to station area
 - (3) Station integrated with commercial area for added convenience